



C.NO/12/FSCR/DFO/BELAGAVI/2025

Date : 24-11-2025

To,
The Principal,
K.L.E Society's,
K.L.E School, Belagavi
Lingaraj College Campus, College Road,
Belagavi, Belagavi Taluk & District.

Sir,

Sub: Issue of '**Fire Safety Compliance Report**' to K.L.E Society's, K.L.E School, Lingaraj College Campus, College Road, Belagavi, Belagavi Taluk & District.

Ref: 1) C.NO/12/FSR/DFO/BELAGAVI/2025 Date: 16-01-2025.
2) C.No:46/FSCR/FSO/Belagavi/2025 Date: 30-08-2025.

*_*_*_*_*_*_*_*_*_*

With reference to the subject above cited, the premises of **K.L.E Society's, K.L.E School**, building consisting with Ground & 2 Upper floors situated at Lingaraj College Campus, College Road, Belagavi, Belagavi Taluk & District was inspected by The Fire Station Officer Belagavi on 18/07/2025 with respect to fire Prevention, Fire Fighting & Evacuation point of view for the purpose of issuing "**Fire Safety Compliance Report**" and has submitted the details as under.

ANNEXURE-1

"GROUP-B Educational Buildings

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory.)

A. Details of the Building/Premises.

01	Name and Address of the Applicant	The Principal, K.L.E Society's, K.L.E School, Belagavi Lingaraj College Campus, College Road, Belagavi, Belagavi Taluk & District.
02	Name and Address of the Premises	K.L.E Society's, K.L.E School, Belagavi Lingaraj College Campus, College Road, Belagavi, Belagavi Taluk & District.
03.	Name and Address of the Building Owner	The President, Karnataka Lingayat Education Society Belagavi.
04.	Number of Building	01
05.	Number of Floors	Ground & 2 Upper Floor
06.	Floor-wise details of Occupancy:-	
	Ground Floor	Class Room-09, Office Room-01, Staff room-01, Library-01, Counsellor Room-01
	1 st Floor	Class Room-10, Staff room-01, Computer Room-01, Art Room-01
	2 nd Floor	Class Room-12, Staff room-01,

[Handwritten Signature]
24/11/25

07.	Height of the building	11.80 Mtr
08.	Site area	66978.19 Sq Mtr.
09.	Built-up area of each floor:-	
	Ground Floor	1205.00 Sq Mtr.
	1 st Floor	1205.00 Sq Mtr.
	2 nd Floor	1205.00 Sq Mtr.
10.	Total Built-up area	3615.00 Sq Mtr.
11.	Surrounding properties:-	
	East	K.L.E Society's B.C.A College
	West	Police Quarters
	North	K.L.E Society's Fashion Designing College
	South	Lingaraj College
12.	Open Space all around the building	
	East	09.00 Mtr
	West	03.20 Mtr
	North	Nil
	South	Nil
Allowed Setbacks (open space) should be maintained free from further obstruction/construction.		

B. On the inspection of this School/College premises, the following Fire Prevention, Fire Fighting and Evacuation Measures recommended are considered absolutely essential from fire safety point of view:-

Sl. No (01)	Details (02)	Existing (03)	Recommendations (04)
01.	Accessibility to the premises	The premises is accessible from 09.00 mtr wide road on the Eastern Side	Adequate
02.	Number of Entrances	02 entrance each of 06 Mtr wide.	Adequate
03.	Number of Staircase	No of staircase	Complied
		03 nos. all are same measurement	
		Width of the staircase	
		01.30 Mtr	
		Width of threads	
		00.29 Mtr	
		Height of risers	00.15 Mtr
		No of risers per flight	
		12 No	
		Height of the hand drill.	0.85 Mtr
04.	Portable Extinguishers	25 nos. of 6 Kg capacity ABC type, 01 no. of 4.5 kg Capacity CO2 type & 01 No. of 9 Ltrs capacity Mechanical Foam type Fire Extinguishers has been provided. All the extinguishers suggested are BIS markings and are located at an easily accessible position without obstructing the normal passagc.	Complied
05.	Hose reel hose system	09 Nos. of Hose reel Hose has been provided. The hose reel hose of min	Complied

Signature
24/11/25

		19 mm size and of 30 mtrs length has been provided to reach the farthest point of each floor and shut off branch having a nozzle of 05 mm size the hose reel hose is connected at staircase landing of the building. And one hose fitted box.	
06.	At the terrace tank level with minimum pressure of 3.5 kg/cm ²	The system has been connected to booster pump of 750 LPM capacity. Further the system also has been connected to alternative source of power supply.	Complied
07.	Diesel Generator	160 & 260 KVA generators has been provided.	Complied.
08.	Terrace Tank	01 no. 30,000 ltrs capacity RCC Overhead Tank has been Provided.	Adequate
09.	Escape routes	Direction in which the students/teachers have to move in the event of emergency has been indicated in the corridor/passage as a guide during evacuation.	Complied.
10.	Fire Order (Fire safety plans)	A notice board indicating the action to be taken by the employees in case of any emergency has been displayed along with the telephone numbers of Belagavi Fire station i.e 0831-2429441, & 101 the telephone no's nearest ambulance services and police station.	Complied
11.	No Smoking board	COPTA Sec-4 direction of No Smoking area, smoking here is an offence board is written in the English & Kannada both languages and is displayed inside the entry/exit.	Complied
12.	Fire Siren	A fire siren has been installed in the premises to inform the students/teachers in case of a fire emergency and evacuate the area.	Complied
13.	Nominate One Fire Nodal Officer	Sri. Hemant Ashtekar & Sri. Shivappa Naik are nominated as fire nodal officer	Nominated
14.	Fire Fighting Training	02 person have been trained in Chaitanya Techno School Belagavi From 02-10-2025 to 03-10-2025 1. Shri. Hemant Ashtekar 2. Shri Shivappa Naik.	At least 40% of the Teaching and non Teaching staff should be got trained in basic fire fighting at R.A.Mundkur Fire & Emergency Services Academy, Bannerughatta Road, Bangalore or Regional training centre Hubballi.
15.	Fire Precautionary Measures A :- Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory and electrical sum panel premises. B:-Accumulation of combustible waste in and around the premises should be avoided. C:- The Exit ways shall be always kept clear without any obstruction. D:-Liquefied petroleum gas should not be stored in the building. E:- The doors shall not be kept locked/ latched during working hours and shall be free from obstruction. F:- During the class hours the class room door shall not be locked from inside to out side.		

Handwritten signature and date
20/10/25

G:- As per Honorable Supreme Court order all teachers and staff shall be trained to handle safety equipments, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year by conducting Fire Safety drills with co-ordination with the fire services department.

Under the above circumstance the Karnataka Fire & Emergency Services Department is issuing "Fire Safety Compliance Report" to K.L.E Society's, K.L.E School, Lingaraj College Campus, College Road, Belagavi, Belagavi Taluk & District. As they have complied all the recommendations as per reference 1. The staff should get trained in the basic fire fighting at R.A.Mundkur Fire & Emergency Services Academy, Bannerughatta Road, Bangalore or Regional training centre Hubballi.

This "Fire Safety Compliance Report" is valid for only one year from the date of issue and is renewable

Yours Faithfully


District Fire Officer
Karnataka State Fire And Emergency Services
Belagavi-01.

Copy to,
Fire Station Officer, Belagavi.




Principal
K.L.E SCHOOL, BELAGAVI